

Manhole Inspection Summary

Manhole # S41E__003MH

Printed On: 3/20/2009

Page 1 of 6

Inspection ☐ Is Incomplete Rating: **3) Fair**

Record Plat: **41E** Node: **003** Status: **Found**

Insp Date: **2/19/09 12:24 PM**

Incomplete Comments

Crew: **benharris**
Inspector: **paulfry**
Firm: **ATS**

Location Address: **1228 E BALTIMORE ST**

Cross Street: **N CENTRAL AVE**

Manhole Type: **Inline** Location: **Roadway** Ground Conditions: **Dry**

☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **Sheeting**

Comments **OBSERVED THAT MANHOLE LID WAS CRACKED AND SEALED WITHIN FRAME. USED 16LB MAUL TO BREAK THROUGH, AND A SAW TO BREAK SEAL. REMOVED AND REPLACED WITH NEW 24" SANITARY LID. INSPECTION COMPLETED USING MAN ENTRY TO OBTAIN ALL PICTURES.**

Cover Shape: **Circular** Diameter: **24** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame Offset: **0** (in.) Condition: ☐ Sound ☒ **Cracked** ☐ Leaks

Chimney / Frame Adjustment ☒ Exists Material: **Brick** ☐ Parged Height: **4** (in.)

Condition: ☐ Sound ☒ **Cracked** ☐ Root Intrusion ☐ Loose Brick ☒ **Deteriorated**

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel Material: **Brick** ☐ Parged Type: **Concentric/Eccentric**

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☒ **Deteriorated**

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel Material: **Brick** ☐ Parged

Shape: **Rectangular** Diameter: **60** (in.) Length: **14** (in.)
4

Condition: ☐ Sound ☒ **Cracked** ☐ Root Intrusion ☐ Loose Brick ☒ **Deteriorated**

Infiltration: ☒ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench ☒ Exists Material: **Brick** ☐ Parged

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel Material: **Brick** ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps Count: **7** Missing: **0** ☒ **Corroded**

Surcharge ☐ Evidence Of Surcharge Depth: **0** (ft.) ☐ Active Surcharge Present

Manhole Inspection Summary

Manhole # S41E__003MH

Printed On: 3/20/2009

Page 2 of 6

Location View



Top View



Miscellaneous



DEBRIS IN CHANNEL

Misc



USED SAW TO BREAK OPEN LID

Misc



REPLACED LID WITH NEW 24" SANITARY

Misc



CONCRETE SLAB OVER BARREL

Manhole Inspection Summary

Manhole # S41E__003MH

Printed On: 3/20/2009

Page 3 of 6

Misc



BROKEN PREVIOUS
MANHOLE-ARRIVED ON SITE TO FIND
LID WELL CRACKED - THIS PICTURE

Miscellaneous



TOP VIEW OF CONNECTIONS FROM
INSIDE BARREL UNDER CONCRETE
SLAB

Defect 6



SEVERELY CORRODED STEP

Misc



BROKEN LID

Defect 7



CRACKED AND BROKEN CHIMNEY
ADJUSTMENT OF 5"

Defect 5



CRACKS AND MISSING MORTAR AT
CORBEL/BARREL JOINT

Defect 2



LARGE CRACK IN FRAME

Manhole Inspection Summary

Manhole # S41E__003MH

Printed On: 3/20/2009

Page 5 of 6

12 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: 0 (in.) Direct

Pipe Material: **Clay** ☐ Pipe Lined

Invert Depth: **12.25** (ft.) Flow Characteristics: **Slow**

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ **Debris** ☐ Grease

Silt Depth: 0 (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

12 in. Circular Gravity Sewer
Pipe In @ 5 O'Clock

5 O'Clock Inflow



Pipe Height: 0 (in.) Direct

Pipe Material: **Clay** ☐ Pipe Lined

Invert Depth: **12.15** (ft.) Flow Characteristics: **Slow**

Deposits: ☒ None ☐ Mud ☐ Sludge ☐ **Debris** ☐ Grease

Silt Depth: 0 (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

☐ Possible Illicit Connection

Manhole Inspection Summary

Manhole # S41E__003MH

Printed On: 3/20/2009

Page 6 of 6

8 in. Circular Gravity Sewer
Pipe In @ 8 O'Clock

8 O'Clock Inflow



Pipe Height: **8.4** (in.) Rod and Bar (Angled)

Pipe Material: **Clay** ☐ Pipe Lined

Invert Depth: **11.10** (ft.) Flow Characteristics: **None**

Deposits: ☐ None ☐ Mud ☐ Sludge ☒ **Debris** ☐ Grease

Silt Depth: **1** (in.) Deposits Extent: **Light**

Infiltration: **None**

Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **House connection / Service line**

☐ Possible Illicit Connection